






“3307”

versionsnummer: 13.09.2023

Naturholz kann sich werkstoffbedingt verziehen. Durch das Montieren ziehen sich Teile wieder plan.



B1

16x φ6.3x50 mm	8x r3
20x s2	16x s1
20x r16	12x r1
	44x φ8x32 mm

B2

2x c105	12x φ3.5x16 mm
4x j30	4x j38
4x j48	4x φ3.5x35 mm
1x z1	

B3

4x n12/1	2x k12
4x n12/2	6x k5
4x l9	8x φ5x17 mm
22x l2	24x φ3.5x13 mm
16x φ6x20 mm	

B4




4x b3	4x a2
--------------	--------------

I

4x  $\phi 15 \text{ #12.5}$ r3




8x  $\phi 15 \text{ #12.5}$ r1

20x  $\phi 8 \times 32 \text{ mm}$ f1




2




3



16x
r16



4



4x
j30



4x
j38

4x
j48



8x
p4
ø3.5x16 mm

6x
k5

2x
k12



13






3

5

4x
b3



8x
e2
 $\phi 6.3 \times 13 \text{ mm}$




6

4x
a2

8x
p1
 $\phi 3.5 \times 13 \text{ mm}$




2x




4

7

4x  $\phi 6 \times 20$ mm e23







8



4x  e1


4x  s1

1x  z1



5


9



4x
e1

4x
s1




1x
z1




e1

e1

e1





10



4x
e1

4x
s1

1x
z1



10




4

13

11


e1

e1






6

11




12



7






13



22x
12



4x
19

4x
φ3.5x16 mm
p4






14

4x
φ6x20 mm
e23




15

8x  $\phi 6 \times 20$ mm e23

















16

8x  $\phi 3.5 \times 13$ mm p1 4x  n12/1



9






17



10

18

8x  ø5x17 mm d1	20x  s2
4x  p42	2x  c105



11